

## Incident INCI031003 for Greater Dublin Area Licence (D0034-02)

### Notification No: INCI031003

Submitted: 28/08/2025 08:58

#### Licensee Details

---

**Organisation:**

Uisce Éireann

**Licence Name:**

Greater Dublin Area

**Reg No:**

D0034-02

**Site Address:**

Dublin

#### Notifier Details

---

**Name:**

Aishwarya kartham

**Address:**

Colville House Talbot Street, Dublin,Ireland ,Dublin,Ireland

**Phone:**

01318925725

**Email:**

aishwarya.kartham@water.ie

#### Details

---

**Description of Incident:**

*Elm Park Golf Club overflow into Elm Park Stream activated during heavy rainfall on 27/08/2025 at 7.58am and ended at approx. 9.30am. Text notification alarm received. The overflow was diluted due to the heavy rainfall at the time. DCC Env. informed.*

**Incident Category:**

Category 1

**Approximate Start of Incident:**

27/08/2025 07:58

**First Noticed:**

27/08/2025 07:59

**Still Ongoing:**

No

**End Date:**

27/08/2025 09:30

**New or Recurring Incident:**

Recurring

**Incident Nature:**

Uncontrolled Release

**Impact of Incident on Environment:**

Combined sewer overflow into Elm Park Stream and subsequently Dublin Bay during heavy rainfall.

**Uncontrolled Release to Receptors:**

Water

**Details of any Vulnerable Receptors:**

Elm Park Stream which enters Dublin Bay

**Likely Cause:**

SWO exceptional rainfall and overflow expected

---

**Incident Location**

**Licensed Discharge Point:** No

**Location Description:** Combined Sewer Overflow in Elm Park Golf Club

---

**Emission Parameter Results**

---

**Communication**

**EPA Informed by Telephone:** No

**EPA Informed Date:**

**EPA Informed Staff Member:**

**EPA Informed Contact Details:**

**Other Communications:**

---

**Additional Details**

**Activity in Process at time of incident:**

Normal activity

**Corrective Actions Taken:**

Action	Name	Date
No corrective action undertaken since CSO operated as designed during heavy rainfall.		27/08/2025 08:05

**Preventive Actions to be Taken:**

Action	Target Date
No preventative action undertaken since CSO operated as designed during heavy rainfall.	27/08/2025 00:00

**Likelihood of Recurrence:** Medium

**Other Relevant Information**

