# Incident INCI027695 for Irish Cement Limited (Limerick) Licence (P0029-06)

Notification No: INCl027695
Submitted: 02/05/2024 18:14
Licensee Details
Organisation:
Irish Cement Limited
Licence Name:
Irish Cement Limited (Limerick)
Reg No:
P0029-06
Site Address:
Castlemungret, Limerick
Notifier Details
Name:
Doireann Funnell
Address:
Castlemungret, Limerick, Ireland
Phone:
061487233
Email:
dfunnell@irishcement.ie
Details
Description of Incident:
Due to an instrument error, the indicated volumetric flowrate of the kiln stack has exceeded the hourly ELV.
Incident Category:
Category 1
Approximate Start of Incident:
29/04/2024 13:25
First Noticed:
02/05/2024 14:33
Still Ongoing: Yes
New or Recurring Incident:
New
Incident Nature:
Other
Impact of Incident on Environment:
None
Uncontrolled Release to Receptors:
No uncontrolled release

Details of any Vulnerable Receptors:

None.

# **Likely Cause:**

Monitoring equipment malfunction/maintenance

### **Incident Location**

Licensed Discharge Point: Yes

P0029-A2-01

**Location Description:** 

#### **Emission Parameter Results**

## Communication

**EPA Informed by Telephone:** No

**EPA Informed Date:** 

**EPA Informed Staff Member: EPA Informed Contact Details:** 

**Other Communications:** 

### **Additional Details**

# Activity in Process at time of incident:

Plant is operating normally.

### **Corrective Actions Taken:**

Action	Name	Date
Verified that the fault is with the measurement equipment.		02/05/2024 16:30

# **Preventive Actions to be Taken:**

Action	Target Date
Instrument to be serviced as	07/05/2024 00:00
soon as possible.	

Likelyhood of Recurrence: Low
Other Revelant Information