

# Certificate Of Collection

## COMPANY DETAILS

COMPANY DETAILS: Irish Cement Ltd

SITE ADDRESS: Plattin Works, Drogheda, Co Louth

## DETAILS OF WASTE RECOVERED BY ENVA

WTF	Date	Quantity (Kg)	EWC Code	Description of waste
LH200924016	21.11.24	520	13 08 02*	Oily sludge

## DETAILS OF RECOVERY

WASTE FACILITY  
JFK Environmental,  
Naas Road, Dublin 12  
W0196-01

WASTE COLLECTION PERMIT  
NWCPO-08-01116-03

ENTERED FACILITY  
21.11.2024

RECOVERY PATH  
JFK Environmental – D9, R13

We hereby certify that the waste detailed above will be treated in accordance with all National and European Waste Legislation.

## CERTIFIED BY:



Niamh Seymour

# Certificate Of Treatment

## COMPANY DETAILS

COMPANY DETAILS: Irish Cement Ltd

SITE ADDRESS: Plattin Works, Drogheda, Co Louth

## DETAILS OF WASTE RECOVERED BY ENVA

WTF	Date	Quantity (Kg)	EWC Code	Description of waste
LH211124002	21.11.24	1260	13 08 02*	Oily water

## DETAILS OF RECOVERY

### WASTE FACILITY

Enva Ireland Ltd.  
W0184-02

### WASTE COLLECTION PERMIT

NWCPO-08-01116-03

### ENTERED FACILITY

21.11.2024

### RECOVERY PATH

Enva Portlaoise – D9, R9, R13

**We hereby certify that the waste detailed above will be treated in accordance with all National and European Waste Legislation.**

### CERTIFIED BY:



Niamh Seymour

Services and Contracts Executive