

Site Visit Report

The site visit process is a sample on a particular day of an installation's compliance with some of its licence conditions. Where non-compliance against a particular condition has not been reported, this should not be construed to mean that there is full compliance with that condition of the licence.

Instructions and actions arising from the visit shall be addressed, or where applicable noted, by the licensee in order to ensure compliance, to improve the environmental performance of the installation and to provide clarification on certain issues.

The licensee shall take the actions specified to close out the non-compliances and observations raised in this Site Visit Report.

The licensee may also be requested to provide a response to the Environmental Protection Agency (hereafter referred to as the Agency) in relation to the site visit report findings.

Licensee	
Name of Installation	Dawn Meats Ireland Unlimited Company
Licensee	Dawn Meats Ireland Unlimited Company
Licence Register No.	P0811-02
CRO Number	135414
Site Address	Greenhills, Beauparc, Navan, Meath
Site Visit Reference No.	SV31155

Report Detail	
Issue Date	19/11/2025
Prepared By	Rachel Barrett

Site Visit Detail			
Date Of Inspection	21/10/2025		
Time In	14:05	Time Out	14:25
EPA Inspector(s)	Eddy Minet		
Additional Visitors	N/A		
Licensee Personnel and Role	N/A		

> Summary

The Agency carried out this site visit as part of the Agency's emissions monitoring programme. The monitoring report is attached.

No discharge at time of visit (14:15 on 21/10/25)

> Site Areas Inspected

Emissions monitoring points and/or sampling locations as specified in attached report.

> Documents Inspected

N/A



EPA Laboratory Test Report

EPA Regional Inspectorate Dublin
McCumiskey House
Richview
Clonskeagh Road
Dublin 14

Final

Report To: OEE Castlebar Office of Environmental Enforcement EPA, John Moore Road, Castlebar,	Project: EPA-25-01981 Report Number : 9014 Entity: P0811-02 Location/Site: Dawn Meats Ireland Site Visit Number: SV31155
--	---

Sample Number: 25-16328	Sampled Date: 21/10/2025
Sampling Point: P0811-SW2	Sampled By: E. Minet
Description: Dawn Meats Ireland Unlimited Company - SW2	Replicate / Split: N/A
Sample Condition: No sample	Grab/Composite: N/A
	Received in Lab: N/A

Parameter	Result	Units	Limits	Measurement Uncertainty	Analysis Date	Lab	Method
Sample Obtained?	No					DB	

Comment: No discharge at time of visit (14:15 on 21/10/25).

Report Approved By: _____
Eimear McKenna - Scientific Officer

Results in bold are outside specified limits, not taking account of measurement uncertainty. * Indicates accredited method. nm = not measured, nr = not reported, vob = visible on bottom. The temperature reading of a **composite** sample is provided to allow the interpretation of the field pH result only.

Field Measurements are performed on the date of sampling. Results relate only to the item tested as received.

This test report shall not be reproduced except in full without approval of the laboratory.

FOLLOW-UP ACTIONS

The licensee is required to complete the actions outlined in this site visit report within the specified timeframes. Where required, the licensee shall also respond to actions specified in Compliance Investigations and/or submit a response to this site visit report via the EDEN system. The licensee shall maintain a documentary evidence, for review by the Agency, that the prescribed actions were completed within the required timeframe.

(i) Compliance Investigations

The Agency may generate a Compliance Investigation through the EDEN system and issue instructions and actions to the licensee. The licensee will receive notification when an instruction or action is issued and the licensee must respond to the actions within the Compliance Investigation within the specified timeframe.

(ii) Response to Site Visit Report

Where the licensee is requested to (or wishes to) respond to the Agency in relation to this site visit report, the licensee may select the 'Make a Response' link on the Site Visits page in EDEN where a .pdf document containing the response can be attached and submitted. The response should include details of the actions taken by the licensee to address the issues raised in this site visit report and the target completion dates. This Licensee Public Response provides the licensee with an opportunity to inform both the Agency and the public about the implementing of actions set out in the Agency site visit report. The response must be submitted **within 21 calendar days** of the issue date of this site visit report.

(iii) Publication of Reports

This site visit report will be published on the EPA's website, www.epa.ie, 30 calendar days after the site visit report issue date.

Any licensee response to this site visit report will be published on the EPA's website simultaneously (i.e. 30 calendar days after the site visit report issue date).

Please note that licensees are required to comply with the conditions of the licence at all times, and where non-compliance occurs, compliance must be restored within the shortest possible time. These actions will be verified during subsequent Agency visits. Please quote the above Inspection Reference Number in any correspondence in relation this Report.